PIG'S EYE LANDFILL RECORDS COMPILATIONS PILLSBURY COMPANY

US EPA RECORDS CENTER REGION 5

Page No. 1 02/27/95

DCN	DATE	AUTHOR	RECIPIENT	TITLE	SUMMARY	PRPS
01020	01/25/80	JEFF HARTHUN	ROBERT JOHNSON	LETTER REGARDING POTENTIAL POLLUTION PROBLEMS NEAR PIG'S EYE	A LETTER WHICH SERVES TO UPDATE THE COMMITTEE ON THE STATUS OF ISSUES DISCUSSED IN A RECENT MEETING REGARDING POTENTIAL SOURCES OF POLLUTION AT PIG'S EYE LAKE - RED ROCK AREA. THE LETTER STATES THE MEETING DISCUSSED THREE POTENTIAL SOURCES OF POLLUTION: NSSTEC, MWCC AND PILLSB. NSSTEC HAD BEEN DEPOSITING METAL SLAG MATERIAL ON RED ROCK ROAD; MWCC OPERATES AN ASH STORAGE BASIN; AND PILLSB HAS CONDUCTED QUESTIONABLE LOADING AND STORAGE OF FERTILIZERS AND SALTS.	NSSTEC, MWCC, PILLSB



JAN-2 5 1980

District 1 Community Council Physical Committee c/o Robert Johnson, Chairman 1989 North Park Drive St. Paul, Minnesota 55119 St. Paul, Minnesota 55119

Continued to a time the little will be able to

RE: Potential Pollution Problems Near Pigs Eye Lake and the Red Rock Area and the state of t

Dear Mr. Johnson: The Land Communication of the Com

This letter shall serve to update your committee on the status of the issues discussed during our recent meeting of January 16, 1980, regarding potential sources of pollution which may exist in the Pigs Eye Lake - Red Rock area.

During our meeting the three (3) potential sources of pollution about which there seemed to be some concern were:

- 1. North Ster Steel Company
- 2. Metropolitan Waste Control Commission
- 3. The Pillsbury Company River Terminal

Committee of the commit

The Minnesota Pollution Control Agency is currently attempting to deal with both existing and potential problems which are resulting or may result from the activities of the above mentioned groups. The following is a brief summary of the current status of each.

The North Star Steel Company has for many years, been depositing metal slag material which is mainly iron, magnesium and calcium oxides into the surface water area along Red Rock Road. While it has been determined that this material is relatively inert, the Minnesota Pollution Control Agency is still requiring that much of this material be pulled back from the surface water area. The specific requirement is that the metal slag material be pulled back from the water such that a distance of 475 feet is maintained between the edge of the stockpile and the centerline of Red Rock Road. This pull-back process is to be accomplished by no later than September 30, 1980. The Minnesota Pollution Control Agency is further requiring that North Star Steel apply for and obtain a permit for future storage of metal slag at this facility. Proper storage controls may than be enforced under various conditions of the permit.

Phone: (612) 297-2726

The Metropolitan Waste Control Commission currently operates an ash storage basin and a grit disposal area on the northern end of Pigs Eye Lake. At this time MWCC is in the process of applying for a permit to excavate the ash from the diked basin as well as the grit from the adjacent area and most likely will propose to spread this material on the surface of the old Pigs Eye dump, a portion of which has not been terminated in accordance with Agency requirements. In the process of excavating these materials, other solid wastes which have been buried with the grit or ash are to be removed to a permitted sanitary landfill. Monitoring wells are already present around the area of the old Pigs Eye dump since this area has been used for ash disposal by MWCC in the past.

marketing of the section of the section of It was indicated by individuals at the meeting that the Pillsbury Company's River Terminal operation has in the past conducted some questionable loading and storage practices involving various fertilizers and salts. The Minnesota Pollution Control Agency enforces a general policy which requires that salts be stored on a reasonably impermeable surface and that a berm or dike be present if necessary to minimize runoff to nearby surface water bodies. The asphalt parking lot area at Pillsbury would seem to qualify as a somewhat impermeable surface, however, Pillsbury may have to construct a more effective berm near the lake bank area if future storage of fertilizers and salts is to occur at this location. Regarding the barge loading and unloading practices and subsequent spillage of fertilizers and salts which may be occurring, this Agency will attempt to obtain further information regarding these practices in the hope of correcting existing spillage problems. The matter of coal storage and stockpiling and subsequent runoff problems which may be occurring at Pillsbury has been referred to the Mirnesota Pollution Control Agency Division of Water Quality. They will be conducting an inspection of the site for the purpose of determining what runoff problems may exist and what corrective actions may be required.

The transfer was an interest the second Any additional information which your organization can provide to this Agency regarding the matters discussed above, will be appreciated. Every attempt will be made to keep you informed of the changing status of these situations. the first of a string of the first of the string of the st

Land the second of the second of the second

Thank you for inviting me to your Physical Committee meeting. Please feel free to contact me or anyone else in this Agency with matters which you feel require our attention. Sincerely, legge as and option small beautiful as the control of the state of the control of the

ing the Salar Office File

Jeff Harthun Pollution Control Specialist Enforcement Section Division of Solid Waste JH:ds

JH:ds Enrique Gentzsch, Ramsey County

: Pat Mader, Division of Water Quality, MPCA